

Heathkit Service Bulletins - HD-8999 (Revised & Complete)

Joseph W Lutz [joelutz at JUNO.COM](mailto:joelutz@JUNO.COM)

Wed Jan 21 00:50:39 EST 1998

- Previous message: [NEED: MANUAL C-3](#)
- Next message: [Heathkit Service Bulletins - HD-4040 \(Revised & Complete\)](#)
- Messages sorted by: [\[date \]](#) [\[thread \]](#) [\[subject \]](#) [\[author \]](#)

September 20, 1985

HD-8999

UltronPro CW Keyboard

Bulletin No:

HD-8999-1

In Manual [PN 595-2941-01], the schematic shows the incorrect labels on the leads of Q12 and Q13. The transistor symbols are correct, however, the labels for the emitter and collector are interchanged. Make this correction to your shop schematic for future reference.

December 20, 1985

HD-8999

UltronPro CW Keyboard

Bulletin No:

HD-8999-2

Seven Segment Display Change

The seven-segment displays at V201-V204 are changed:

From [PN 411-861] to [PN 411-884].

Thats everything I hold up to 1989 that covers the HD-8999. Enjoy!

73 de Joe W7LPF/4 [NNN0KUU]
 QWCA - SOWP - NCVA - FISTS - RCC
 Gordonsville, Va 22942 [Orange Co]

To subscribe: [listserv at listserv.tempe.gov](mailto:listserv@listserv.tempe.gov)
 and in body: subscribe HEATH yourfirstname yourlastname
 To unsubscribe: [listserv at listserv.tempe.gov](mailto:listserv@listserv.tempe.gov)
 and in body: signoff HEATH
 Archives for HEATH: <http://www.tempe.gov/archives>

-
- Previous message: [NEED: MANUAL C-3](#)
 - Next message: [Heathkit Service Bulletins - HD-4040 \(Revised & Complete\)](#)
 - **Messages sorted by:** [\[date \]](#) [\[thread \]](#) [\[subject \]](#) [\[author \]](#)
-

[More information about the Heath mailing list](#)